Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

 O102
 YBC AUTO REPAIR INC
 NY UST
 U002258746

 WNW
 2702 STILLWELL AVENUE
 N/A

1/8-1/4 0.193 mi.

1017 ft. Site 2 of 3 in cluster O

BROOKLYN, NY 11224

 Relative:
 UST:

 Higher
 Name:
 YBC AUTO REPAIR INC

 Actual:
 Address:
 2702 STILLWELL AVENUE

 2 ft.
 City,State,Zip:
 BROOKLYN, NY 11224

 Id/Status:
 2-016047 / Active

Program Type: PBS
Region: STATE
DEC Region: 2

Expiration Date: 06/01/2024 UTM X: 586115.26809 UTM Y: 4492745.71907

Site Type: Other

Affiliation Records:

Site Id: 104

Affiliation Type: Facility Owner
Company Name: MARA HANUKOV
Contact Type: PRESIDENT
Contact Name: CHRIS NG

Address1: 2702 STILLWELL AVE

Address2: Not reported City: BROOKLYN State: NY Zip Code: 11224 Country Code: 001

Phone: (917) 537-1800
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-12

Site Id: 104

Affiliation Type: Facility Operator

Company Name: YBC AUTO REPAIR INC

Contact Type: Not reported
Contact Name: CHRIS NG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Zip Code: Not reported Country Code: 001

Phone: (718) 513-0881
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-08-20

Site Id: 104

Affiliation Type: Emergency Contact
Company Name: MARA HANUKOV
Contact Type: Not reported
Contact Name: CHRIS NG
Address1: Not reported

Map ID MAP FINDINGS

Direction Distance Elevation

Site EDR ID Number

Database(s) EPA ID Number

Address2: Not reported City: Not reported State: NN

Zip Code: Not reported Country Code: 999

Phone: (917) 519-2731
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-08-20

Site Id: 104

Affiliation Type: Mail Contact

Company Name: YBC AUTO REPAIR INC

Contact Type: Not reported Contact Name: CHRIS NG

Address1: 2702 STILLWELL AVE

 Address2:
 Not reported

 City:
 BROOKLYN

 State:
 NY

 Zip Code:
 11224

 Country Code:
 001

Phone: (718) 513-0881
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-12

Tank Info:

 Tank Number:
 001

 Tank ID:
 26925

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 6600
Install Date: 12/01/1963
Date Tank Closed: 12/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0003

Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None D01 - Pipe Type - Steel/Carbon Steel/Iron H00 - Tank Leak Detection - None I04 - Overfill - Product Level Gauge (A/G) J02 - Dispenser - Suction Dispenser

G07 - Tank Secondary Containment - Excavation Liner

B00 - Tank External Protection - None C00 - Pipe Location - No Piping

Map ID		MAP FINDINGS		
Direction		4		
Distance				EDR ID Number
Elevation	Site		Database(s)	EPA ID Number

F00 - Pipe External Protection - None